

00862.002400.2



COFE
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: T. Vo
ATSUSHI DATE, et al.)	
	:	Group Art Unit: 2112
Appl. No.: 09/917,833)	
	:	
Filed: July 31, 2001)	
	:	
For: BUS MANAGEMENT BASED)	
ON BUS STATUS	:	
	:	
U.S. Patent No.: 7,062,664 B2)	
	:	
Issued: June 13, 2006)	November 22, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULE 322

Certificate
NOV 28 2006
of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

NOV 29 2006

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Michael K. O'Neill", written over a horizontal line.

Michael K. O'Neill
Attorney for Patentees
Registration No.: 32,622

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 122869v1.

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,062,664 B2

DATED : June 13, 2006

INVENTOR(S) : Atsushi Date, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 38, "PCi" should read -- PCI --.

COLUMN 14:

Line 1, "and 803" should read -- and 1ru 803 --.

COLUMN 16:

Line 30, "SEB" should read -- SBB --.

COLUMN 18:

Lines 25 to 26, "bWBurstReq L," should read -- bWBurstReq_L, --;

Line 29, "b (Slavename)" should start on a new line; and

Line 65, "laneonbData[31:0]" should read -- lane on bData[31:0] --.

COLUMN 19:

Line 10, "bBurst L" should read -- bBurst_L --; and

Line 14, "bBurs tAck_L" should read -- bBurstAck_L --.

COLUMN 36:

Line 36, "bus IO" should read -- bus/IO --.

COLUMN 37:

Line 24, "Gbus IO bus" should read -- G bus/IO bus --; and

Line 27, "G bus IO" should read -- G bus/IO --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,062,664 B2

No. of add'l. copies
@ 30¢ per page



NOV 29 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,062,664 B2

DATED : June 13, 2006

INVENTOR(S) : Atsushi Date, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 38, "PCi" should read -- PCI --.

COLUMN 14:

Line 1, "and 803" should read -- and 1ru 803 --.

COLUMN 16:

Line 30, "SEB" should read -- SBB --.

COLUMN 18:

Lines 25 to 26, "bWBurstReq L," should read -- bWBurstReq_L, --;

Line 29, "b (Slavename)" should start on a new line; and

Line 65, "laneonbData[31:0]" should read -- lane on bData[31:0] --.

COLUMN 19:

Line 10, "bBurst L" should read -- bBurst_L --; and

Line 14, "bBurs tAck_L" should read -- bBurstAck_L --.

COLUMN 36:

Line 36, "bus IO" should read -- bus/IO --.

COLUMN 37:

Line 24, "Gbus IO bus" should read -- G bus/IO bus --; and

Line 27, "G bus IO" should read -- G bus/IO --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,062,664 B2

No. of add'l. copies
@ 30¢ per page



NOV 29 2006